



EMERGENCY MEMORY RECALL (PA-28-235)

ENGINE FIRE DURING START

ENGINE FIRE IN FLIGHT

ELECTRICAL FIRE (SMOKE IN CABIN)

SPIN RECOVERY

CARBURETOR ICING

LOSS OF FUEL PRESSURE

ENGINE POWER LOSS DURING TAKEOFF

ENGINE POWER LOSS DURING FLIGHT

If Altitude Permits:

AP MALFUNCTION / PITCH TRIM RUNAWAY

AP ESP ACTIVATION

OVERSPEED PROTECTION (MAXSPD)

UNDERSPEED PROTECTION (MINSPD)